The Potential for Arrhythmia during Central Venous Catheter Insertion- to where does the guidewire migrate?

Daphna Reichmann (✉ daphna221@gmail.com)

Soroka Hospital: Soroka Medical Center <https://orcid.org/0000-0002-5152-8919>

Re'em Sadeh

Soroka medical center

Ori Galante

Soroka medical center

Yaniv Almog

Soroka medical center

Victor Novack

Soroka medical center

Lior Fuchs

Soroka medical center

Original research

Keywords: Central venous catheters, Location, extra systole, guidewire insertion, tachyarrhythmias, catheter tip location, Right Atrium, Inferior vena cava, Superior vena cava, Trans thoracic echocardiography

Posted Date: January 19th, 2021

DOI: <https://doi.org/10.21203/rs.3.rs-147821/v1>

License: © ⓘ This work is licensed under a Creative Commons Attribution 4.0 International License.

[Read Full License](#)

Abstract

Background

Central Venous Catheters (CVC) are being used in both intensive care units and general wards for multiple purposes. A previous study¹ observed that during CVC insertion through Subclavian Vein (SCV) or the Internal Jugular Vein (IJV) the guidewire is sometimes advanced to the Inferior Vena Cava (IVC), and at other times to the right atrium. The rate of IVC wire cannulation and the association with side and point of insertion is unknown.

Objective

In this study, we describe guidewire migration location during real time CVC cannulation (right atrium versus IVC) and report the association between the insertion site and side of the CVC and the location of guidewire migration, Right Atrium (RA)/Right Ventricle (RV) versus IVC guidewire migration.

Design

This is a retrospective study of the prospectively and systematically collected data on CVC insertion under real time trans thoracic ultrasound.

Setting

The medical Intensive Care Unit in Soroka Medical Center, among patients that have received CVC during the study years 2014–2020.

Main outcome measures:

The rate of IVC versus right atrium/right ventricle wire migration during the procedure were analyzed. The association between the side and point of CVC insertion and the wire migration site was analyzed as well.

Results

One hundred and sixty-six patients were enrolled. 33.7% of wires migrated to the IVC and 66.3% to the versus right atrium/right ventricle. The rate of wire migration to the IVC was similar in the IJV site and the SCV site. There was no association between the side of CVC insertion and wire migration to the IVC.

Conclusion

About a third of all wire migrations, during CVC Seldinger technique insertion, were identified in the IVC, with no potential for wire associated arrhythmia. There was no association between CVC insertion point (SCV versus IJV) nor the side of insertion and the site of guidewire migration.

Introduction

Central Venous Catheters (CVC) are being used in both intensive care units and general wards for multiple purposes. During CVC cannulation, some complications may occur. One of those complications is Extra systole or arrhythmia that can be caused due to irritation of the endocardium by the metallic guidewire, especially if the guidewire is inserted to an excessive depth^{2,3}. This phenomenon is not rare. A previous study⁴ found that 41% of procedures resulted in atrial arrhythmias, and 25% produced some degree of ventricular ectopy.

Most arrhythmias resolve spontaneously or when the guidewire is withdrawn to an adequate depth². Studies have shown that the most common arrhythmia associated with guidewire insertion is atrial premature contraction^{2,5}. However, there is also evidence of potentially life threatening arrhythmias such as persistent supra ventricular tachycardia⁶, complete heart block⁷ and sustained ventricular tachycardia that subsequent cardiac arrest⁸ following the procedure. Wire irritation to the endocardium should be avoided to prevent these rare but dangerous complications.

The risk factors for developing an arrhythmia include insertion of wire longer than 20 cm², female gender and patient height of under 170 cm⁵, and CVC insertion from the right subclavian position.⁴ These factors indicate that the higher chances of tip entering right atrium or ventricle, the greater the chance of arrhythmia.

Guidelines for CVC insertion specify methods for verifying venous guidewire cannulation before dilation of the vein. Methods for confirming that the wire resides in the vein include, but are not limited to trans-esophageal echocardiography (identification of the wire in the superior vena cava or right atrium), continuous electrocardiography (identification of narrow-complex ectopy), or fluoroscopy.⁹ None of these methods are routinely practiced, and performers insert the guidewire to a random length, sometimes causing short extrasystole (when the wire touches the endocardium) as verification for venous wire cannulation.

There is wide variation in distance from skin puncture site (internal jugular versus subclavian) and side of puncture (right versus left) and the right atrial-cava junction. One study measured these distance variations and found 12 cm-25 cm gap.¹⁰ There is no “one size fits all” distance to avoid endocardial irritation during CVC wire insertion.

A previous study¹, by our group describing the utilization of point of care ultrasound for CVC tip placement, observed that during CVC insertion through Subclavian Vein (SCV) or the Internal Jugular Vein (IJV) the guidewire is sometimes advancing to the Inferior Vena Cava (IVC), and in other times to the right atrium. When the guidewire went to the IVC there was no extra-systole.

In this study, we thought to describe guidewire migration location during real time CVC cannulation (right atrium versus IVC), and to report the association between the insertion site and side of the CVC (internal jugular versus subclavian, right side versus left side) and the location of guidewire migration, Right Atrium(RA)/Right Ventricle (RV) versus IVC guidewire migration.

The importance of this finding is related to the fact that guidewire migration to the IVC will not result in arrhythmia or an extrasystole, whereas guidewire migration to the right heart has the potential for arrhythmia. To our knowledge, the chance for arrhythmia during guidewire insertion, hence the ratio of wire migration to the IVC versus the RA was never described before.

Material And Methods

Study population

This cohort study included one hundred and sixty-six patients admitted between 2014 and 2020 in the ICU in Soroka University Medical Center who have required upper torso CVC (SCV or IJV) using Seldinger guidewire insertion.

Patients were excluded if they had recent abdominal surgery precluding the subcostal view or if real time point of care ultrasound guidewire verification could not be made, or that the guidewire location was unknown.

This is a retrospective study of the prospectively and systematically collected data on CVC insertion under real time trans thoracic ultrasound. The data was collected from the medical ICU in the Soroka medical center database of documented central lines inserted during the study years. Many of these central lines were inserted under real time ultrasound guidance with documentation of the guidewire migration site during the procedure. This was done as part of the protocol of central line insertion that was developed in this ICU⁶ and is part of the routine of CVC insertion.

We documented the date, the site and side of insertion, and the location where the guidewire tip was identified in the right heart or the IVC. Also, in random cases, we have documented if there were extrasystole or arrhythmias noticed on the monitor.

CVC Procedure

All catheters were inserted percutaneously using the Seldinger technique. It was inserted on one of four sites: The right internal jugular vein, The left internal jugular vein, The right subclavian vein, and the left subclavian vein. When the procedure was over, the guidewire's location was verified using a trans thoracic US in the subcostal view, it was documented, and the CVC was sutured to the skin and covered sterilely.

Use of US

There was a use of cardiac US during the procedure to identify the location of the tip of the guidewire inserted to the right heart or IVC in real-time, and to measure the depth of the guidewire when the tip of the guidewire is in the SVC. This is the method that we use, as the standard of care, for CVC insertion under US guidance for proper CVC tip placement as further explained in our previous study ¹.

The subcostal view is being used while inserting the guidewire to the central vein. Using the US, we look for the tip of the guidewire in the heart. Then we document if the guidewire went to the IVC, to the RA, or RV. The guidewire will be pulled back until the tip of the guidewire is seated in the SVC. Then the depth of the wire from the skin to the SVC is measured and documented, this is the depth that the central line will be inserted into.

Ethics

This study was approved by the Helsinki committee of the Soroka Medical Center, Beer Sheva, Israel (Chairperson Prof R. HersHKovitz) on 12 July 2018.

Statistical analysis

Patient characteristics are presented as mean $\pm$ SD for continuous variables with a normal distribution and categorical variable are presented as frequency (%).

In our univariable tests we compared means using the independent-samples t-test and compared proportions using Chi square test and Fisher exact test.

To examine the guidewire migration (IVC vs RA/RV) a logistic regression was conducted with the insertion site being the primary independent variable. Variables having clinical significance were add to the regression. An odds ratio (OR), P-value and confidence interval was reported.

A two-sided P-value < 0.05 was considered statistically significant for all statistical tests. P-values reported was rounded to two decimal places. All statistical analyses were performed using SPSS version 24.0 (IBM Corp, 2015).

Results

Two hundred and seven patients were admitted to the medical ICU in Soroka University Medical Center in the years 2014–2020 who have required upper torso CVC insertion. Forty-one were excluded from this study due to missing data (see Fig. 1). One hundred and sixty-six CVC cannulations from the IJV or the SCV were conducted and documented in this study. There were no differences in most of baseline characteristics between the two groups. Table 2 and Table 4 explicit the baseline characteristics of the patients in the study.

Figure 1

Two thirds of upper torso CVC were inserted to the subclavian vein (64%) and a third to the internal jugular vein. About two thirds of CVCs were inserted from the right side (68.7%). About two thirds of wires migrated to the RA/RV and a third to the IVC (Table 2).

Table 1
Patients Baseline Characteristics

	IJV N = 59	SCV N = 107	p-value
Demographic Characteristics			
Gender, male N (%)	40 (69%)	78 (73.6%)	0.52
Age, mean $\pm$ SD	55.3 $\pm$ 17.09	54.3 $\pm$ 19.1	0.72
BMI > 30, N (%)	15 (31.3%)	31 (34.1%)	0.73
Smoking, yes N (%)	12 (22.6%)	31 (30.4%)	0.30
Co- morbidities			
CKD	7 (11.6%)	6 (5.6%)	0.15
HF	8 (13.6%)	11 (10.3%)	0.52
CV disease, yes N (%)	0	11 (10.3%)	0.008
Hyperlipidemia, yes N (%)	14 (23.7%)	28 (26.2%)	0.72
Anemia, yes N (%)	7 (11.9%)	3 (2.8%)	0.019
DM, yes N (%)	15 (24.5%)	27 (25.2%)	0.97
HTN, yes N (%)	27 (45.8%)	43 (40.2%)	0.48
COPD, yes N (%)	8 (13.6%)	9 (8.4%)	0.29
Arrhythmias, yes N (%)	6 (10.2%)	15 (14%)	0.47

Table 2
Site and side of CVC insertion and wire
migration site

Total	166	
Tip placement	IVC	56 (33.7%)
	RA\RV	110 (66.3%)
Site insertion	IJV	59 (35.5%)
	SCV	107 (64.5%)
Side of insertion	Right	112 (68.7%)
	Left	52 (31.3%)

Although we had no systematic data collection of arrhythmias or extrasystoles documentation during CVC insertion, all 15 documented arrhythmias occurred when the wire migrated to the RA/RV and not when IVC wire migration was documented.

The site of CVC insertion was not associated with IVC or RA/RV wire migration (33.9% versus 33.6, IJV and SCV respectively, $P = 0.97$, Table 3a). The side of CVC insertion was also not associated with IVC or RA/RV wire migration ($P = 0.22$ Table 3b), nor the side and site together ($P = 0.66$, Table 3c). The Logistic regression model for wire migration location was not influenced by the side or the site of the CVC (Table 4).

Table 3. CVC insertion site and side

Table 3 a.

	IJV	SCV	p-value
	N = 59	N = 107	
Wire migration site, IVC N (%)	20 (33.9%)	36 (33.6%)	0.97
Side of insertion, right N (%)	39 (66.1%)	75 (70.1%)	0.59

Table 3 b.

	Right	Left	p-value
	N = 114	N = 52	
CVC tip placement, IVC N (%)	35 (30.7%)	21 (40.4%)	0.22

Table 3 c.

Right side

	IJV	SCV	p-value
	N = 39	N = 75	
CVC tip placement, IVC N (%)	13 (33.3%)	22 (29.3%)	0.66

Table 4

Logistic regression; tip placement in the RA\RV

	OR (CI)	p-value
Insertion site, SCV	0.98 (0.5, 1.9)	0.97
Insertion side, Left	0.65 (0.3, 1.2)	0.22

Discussion

We have found that during the insertion of CVC using the Seldinger technique, 33% of guidewires migrate to the IVC, with no potential for any guidewire induced arrhythmia. We also found no association between site and side of CVC insertion and the site of guidewire migration; hence choosing the subclavian over the internal jugular on any side will not increase the rate of guidewire migration to the IVC or the RA/RV.

We believe that physicians who perform central venous catheter insertion should be familiar with the relatively high IVC guidewire migration prevalence.

Some operators verify the “correct” location of the wire when there is tachycardia on the monitor. This technique should not be encouraged for wire placement confirmation because of the risk for right heart guidewire migration hence the potential risk for life-threatening arrhythmia and low sensitivity for such tachycardia. We show that over 30% of cases will not have the potential for tachyarrhythmia. Also, Performers should know that choosing a specific site of insertion (SCV versus IJV) or specific side (right versus left) will not increase or reduce the chance for RA/RV guidewire migration, hence, the chance for iatrogenic arrhythmia.

There are a few possible limitations to this study. First, all the patients in the study were treated in the same medical ICU in Soroka medical center and by a limited number of senior physicians and residents, limiting the generalizability. Secondly, extrasystole was not routinely documented, so although the documented ones occurred only when the wire was identified in the RA/RV, we did not design the study to prove this observation. Lastly, only 20 patients received left-sided IJV CVC. This limited sample size may influence the results as well.

Conclusions

Clinicians who perform upper torso CVC insertion should be aware that 33% of guidewires migrates to the IVC, and not to the RA/RV. When a guidewire migrates to the IVC, no extrasystole is observed.

There was no association between the site of insertion, side of insertion, and the site of guidewire migration. Tachycardia on the monitor should not be used as a sign for correct placement of the central line during this procedure.

Declarations

Ethics approval and consent to participate: This study was approved by the Helsinki committee of the Soroka Medical Center (Chairperson Prof R. Hershkovitz) on 12 July 2018.

Consent for publication: Not applicable.

Availability of data and materials: The datasets used and analyzed during the current study is available from the corresponding author on reasonable request.

Competing interests: The authors declare that they have no competing interests.

Funding: none.

Authors' contributions

DR- writing the manuscript, data collection.

RS- data collection, data analysis.

OG- data collection and the study design.

YA- study design.

VN- study design, data analysis.

LF- study design, data collection, data analysis, writing parts of the manuscript.

Acknowledgements Not applicable.

References

1. Galante O, Slutsky T, Fuchs L, et al. Single-Operator Ultrasound-Guided Central Venous Catheter Insertion Verifies Proper Tip Placement. 2017;1-7. doi:10.1097/CCM.0000000000002500
2. Lee JM, Lee J, Hwang JY, et al. Randomized comparison of three guidewire insertion depths on incidence of arrhythmia during central venous catheterization. *Am J Emerg Med.* 2017;35(5):743-748. doi:10.1016/j.ajem.2017.01.016
3. Polderman KH, Girbes AR. Central venous catheter use part 1: Mechanical complications. *Intensive Care Med.* 2002;28(1):1-17. doi:10.1007/s00134-001-1154-9
4. Stuart RK, Shikora SA, Akerman P, et al. Incidence of Arrhythmia with Central Venous Catheter Insertion and Exchange. *J Parenter Enter Nutr.* 1990;14(2):152-155. doi:10.1177/0148607190014002152
5. Lee T, Sung C, Chu Y, Liou JT, Lui P. Incidence and Risk Factors of Arrhythmia During Internal Jugular Venous Catheterization: Comparison of Marked and Plain J-Wires. 1996;8180(96):348-351.
6. Da Silva PSL, Waisberg J. Induction of life-threatening supraventricular tachycardia during central venous catheter placement: An unusual complication. *J Pediatr Surg.* 2010;45(8):13-16. doi:10.1016/j.jpedsurg.2010.05.013
7. Chhabra L, Spodick DH. Complete heart block - An underappreciated serious complication of central venous catheter placement. *J Electrocardiol.* 2012;45(6):790-792. doi:10.1016/j.jelectrocard.2012.06.005
8. Flannery KR, Wilson SP, Manteuffel J. American Journal of Emergency Medicine Ventricular tachycardia cardiac arrest during central line placement ☐. *Am J Emerg Med.* 2016;34(1):114.e3-114.e4. doi:10.1016/j.ajem.2015.04.064

9. Guide- P, Focus C. Practice Guidelines for Central Venous Access A Report by the American Society of Anesthesiologists Task Force on Central Venous Access. 2012;(3).
10. Andrews RT, Bova DA, Venbrux AC. How much guidewire is too much? Direct measurement of the distance from subclavian and internal jugular vein access sites to the superior vena cava-atrial junction during central venous catheter placement.

Figures

Figure 1

Two thirds of upper torso CVC were inserted to the subclavian vein (64%) and a third to the internal jugular vein. About two thirds of CVCs were inserted from the right side (68.7%). About two thirds of wires migrated to the RA/RV and a third to the IVC (Table 2).